

Highland Country: Fleetlist, 31 January 2006

007	IN	YJ 05 XOB	Oe M???	001900	Oe		B31F	May-05	Rapson (SN)	Jun-05	
008	P	YJ 05 XOC	Oe M950	001901	Oe		B31F	May-05	Rapson (SN)	Jun-05	
009	A	YJ 05 XOD	Oe M???	001902	Oe		B31F	May-05	Rapson (SN)	Jun-05	
010	A	YJ 05 XOE	Oe M???	001903	Oe		B31F	May-05	Rapson (SN)	Jun-05	
011	IN	YJ 05 XOF	Oe M???	002030	Oe		B35F	Jun-05	Rapson (SN)	Jun-05	
012	IN	YJ 05 XOG	Oe M???	002031	Oe		B35F	Jun-05	Rapson (SN)	Jun-05	
035	F	K504 NST	MB 811D	670303-2N-005169	Wt	P226	B31F	Jun-93	Rapson (SN)	Jun-05	
038	IN	M623 WAS	MB 811D	670303-2N-030693	ArB	M43.02	B33F	Apr-95	Rapson (SN)	Jun-05	
040	F	P111 JDP	Fd Tt	BDVETD95540	Fd		M14	Oct-96	Orkney Coaches (SN)	Aug-05	
041	IN	P677 VJS	MB 814D	670313-2N-046689	WS	5455/96	C25F	Dec-99	Rapson (SN)	Jun-05	JN 88 AA
043	P	P343 JAS	MB 814D	670313-2N-046491	WS	5457/96	C25F	Dec-99	Rapson (SN)	Jun-05	JN 90 AA
044	IN	KSU 674	Oe MR15	VN2070	Oe	2070	B32F	Aug-96	Orkney Coaches (SN)	by8/05	P904 DST
045	A	P905 DST	Oe MR15	VN2071	Oe	2071	B32F	Dec-99	Rapson (SN)	Jun-05	
046	IN	YSU 882	Oe MR15	VN2072	Oe	2072	B32F	Dec-99	Rapson (SN)	Jun-05	P906 DST
047	F	P907 DST	Oe MR15	VN2073	Oe	2073	B32F	Dec-99	Rapson (SN)	Jun-05	P907 DST, FSU 797
048	F	T133 AST	Oe MR17	VN2311	Oe	2311	B29F	Mar-99	Rapson (SN)	Jun-05	
053	P	P611 RGB	MB 711D	669063-2N-046470	Adn	AC711002	C24F	Sep-96	Rapson (SN)	Jun-05	
054	T	P612 RGB	MB 609D	668063-2N-046609	Adn	AC609003	C24F	Dec-96	Rapson (SN)	Jun-05	
055	T	P166 LSC	MB 609D	668063-2N-040599	Onyx	143	C24F	Aug-96	Rapson (SN)	Jun-05	
066	wdn	H166 WWT	Oe MR03	VN1059	Oe	1059	B26F	May-91	Rapson (SN)	Jun-05	
071	IN	K314 YKG	MB 811D	670303-2N-001614	Wt	P150	B33F	Oct-92	Rapson (SN)	Jun-05	
072	IN	K316 YKG	MB 811D	670303-2N-001791	Wt	P149	B33F	Oct-92	Rapson (SN)	Jun-05	
073	IN	J414 PRW	MB 811D	670303-2P-152732	Wt	N121	B33F	Oct-91	Rapson (SN)	Jun-05	
075	IN	W691 NST	MB O814D	WDB6703742N088339	Pn	-?	B33F	May-00	Rapson (SN)	Jun-05	
076	P	W692 NST	MB O814D	WDB6703742N088373	Pn	-?	B33F	May-00	Rapson (SN)	Jun-05	
077	IN	K310 YKG	MB 811D	670303-2N-001479	Wt	P152	B33F	Oct-92	Rapson (SN)	Jun-05	
078	IN	L 35 OKV	MB 811D	670303-2N-012611	Wt	S41	B33F	Aug-93	Rapson (SN)	Jun-05	
082	IN	N109 WRC	MB 811D	670303-2N-036074	Pn	958.5MLV4535	B30F	Nov-95	Rapson (SN)	Jun-05	
083	KY	N103 WRC	MB 811D	670303-2N-029573	Pn	958.5MLV3626	B30F	Nov-95	Rapson (SN)	Jun-05	
084	IN	N106 WRC	MB 811D	670303-2N-023566	Pn	958.5MLV4536	B30F	Dec-95	Rapson (SN)	Jun-05	
085	T	M243 JHB	MB 811D	670303-2N-019785	Pn	948.5MLV2255	B31F	Aug-94	Rapson (SN)	Jun-05	
086	T	K325 YKG	MB 811D	670303-2N-005516	Wt	P238	B33F	Jan-93	Rapson (SN)	Jun-05	
087	T	S751 SCJ	MB O814D	6703742N079046	PMT	988.5MXV9872	B31F	Nov-98	Rapson (SN)	Jun-05	S751 SCJ, FSU 797
088	T	T993 PFH	Ta BB50R	0001343	Co	851153	C21F	Jul-99	Rapson (SN)	Jun-05	
098	T	YK 04 KWH	Oe M850	SAB19000000001488	Oe		B26F	Jun-04	Rapson (SN)	Jun-05	
133	wdn	OSK 620V	LN NL116L11/1R (DAF)	06799	LN		B50F	Mar-80	Rapson (SN)	Jun-05	DOC 36V
164	T	MBZ 6454	Vo B10M-61	8083	EL 12/91	B1402	B55F	Jan-85	Rapson (SN)	Jun-05	B572 AVW, URY 598
165	T	HIL 7467	Vo B10M-61	5786	EL 11/91	B1401	B55F	Apr-83	Rapson (SN)	Jun-05	FUA 387Y, 3408 WY, NRV 859Y
167	KY	C 55 HOM	Vo B10M-55	10230	Ar	6P/1085/1	B50F	Mar-86	Rapson (SN)	Jun-05	
168	KY	C 56 HOM	Vo B10M-55	10231	Ar	6P/1085/2	B50F	Mar-86	Rapson (SN)	Jun-05	
169	KY	C 57 HOM	Vo B10M-55	10232	Ar	6P/1085/3	B50F	Mar-86	Rapson (SN)	Jun-05	
170	KY	C 58 HOM	Vo B10M-55	10233	Ar	6P/1085/4	B50F	Mar-86	Rapson (SN)	Jun-05	
171	KY	C 59 HOM	Vo B10M-55	10234	Ar	6P/1085/5	B50F	Mar-86	Rapson (SN)	Jun-05	
175	T	B857 XYR	Vo B10M-61	10264	EL 3/92	B1711	B49F	Apr-85	Rapson (SN)	Jun-05	B857 XYR, XIJ 602
176	T	KXI 434	Vo B10M-61	010265	EL 3/92	B1714	B49F	May-85	Rapson (SN)	Jun-05	B858 XYR
178	F	B860 XYR	Vo B10M-61	010267	EL 3/92	B1710	B49F	May-85	Rapson (SN)	Jun-05	
181	T	JST 224N	LN 11351/2R(Vo)	01813	LN		B41F	Feb-75	Rapson (SN)	Jun-05	GFJ 663N, JIL 7606, GFJ 663N, KKZ 5534
182	T	KRE 278P	LN 11351/1R(Vo)	02562	LN		B41F	Sep-75	Rapson (SN)	Jun-05	KRE 278P, LIL 3059
183	T	KHT 121P	LN 11351/1R(Vo)	03277	LN		B41F	Jun-76	Rapson (SN)	Jun-05	
196	F	J610 KCU	Ds Dt	9.8SDL3017/681	Wt	P9	B40F	Dec-91	Rapson (SN)	Jun-05	
197	F	J623 KCU	Ds Dt	9.8SDL3017/706	Wt	P226	B40F	Feb-92	Rapson (SN)	Jun-05	
198	A	N 4 SKY	MB O405	3.57001E+13	Oe	7076	B51F	May-96	Rapson (SN)	Jun-05	
199	IN	M211 YAS	MB O405	3.57001E+13	Oe	7001	B49F	Mar-95	Rapson (SN)	Jun-05	M926 TYG, M 6 SKY
200	IN	P817 EST	Ds Dt	9.8SDL3017/1326	Pn	939.8HPN1214	B43F	Oct-96	Rapson (SN)	Jun-05	
201	IN	S388 JPS	MAN 11.220	WMA4692389G115937	MI	MAN-032	B36F	Nov-98	Rapson (SN)	Jun-05	

202	IN	S389 JPS	MAN 11.220	WMA4692387G115892	MI	MAN-033	B36F	Nov-98	Rapson (SN)	Jun-05	
205	IN	T132 AST	Vo B10BLE	004798	Wt	A663	B45F	Mar-99	Rapson (SN)	Jun-05	
207	IN	V 32 JST	Vo B6BLE	YV3R3A912XC010071	Wt	B418	B37F	Sep-99	Rapson (SN)	Jun-05	
208	IN	W747 NAS	Vo B10BLE	YV3R4A512XA005385	Ar	9910/15	B44F	Jul-00	Rapson (SN)	Jun-05	
209	IN	Y336 VST	Sca L94UB	1835475	Wt	D535	B43F	Apr-01	Rapson (SN)	Jun-05	
212	F	JAZ 9851	Oe L1150	VN9066	Oe	9066	B45F	Jan-97	Rapson (SN)	Jun-05	P275 NRH, OXI 413
213	F	GAZ 4632	Oe L1150	VN9067	Oe	9067	B45F	Jan-97	Rapson (SN)	Jun-05	P276 NRH, OXI 459
214	F	JAZ 9857	Oe L1150	VN9068	Oe	9068	B45F	Jan-97	Rapson (SN)	Jun-05	P277 NRH, NXI 327
215	IN	X461 UKS	Ds Dt SLF	SFD466BR1YGW30328	Ar	0018/1	DP43F	Sep-00	Rapson (SN)	Jun-05	
216	IN	X462 UKS	Ds Dt SLF	SFD466BR1YGW30329	Ar	0018/2	DP43F	Sep-00	Rapson (SN)	Jun-05	
217	IN	X467 UKS	Ds Dt SLF	SFD466BR1YGW35023	Ar	0018/7	DP43F	Sep-00	Rapson (SN)	Jun-05	
299	IN	YJ 04 HLC	DAF SB200	-?-	Wt	-?-	B??F	Apr-04	Rapson (SN)	Jun-05	
301	T	RAN 645R	BI VRT/SL3/6LXB	VRT/SL3/847	ECW	22386	H43/34F	Jun-77	Rapson (SN)	Jun-05	
302	IN	SAS 859T	Ld FE30AGR	7803340	ECW	23504	H43/32F	Nov-78	Rapson (SN)	Jun-05	
306	IN	ECS 882V	Ld FE30AGR	7800826	NC	8622	H44/31F	Oct-79	Rapson (SN)	Jun-05	
307	A	BKE 832T	BI VRT/SL3/6LXB	VRT/SL3/1754	ECW	22940	H43/31F	Feb-79	Rapson (SN)	Jun-05	
308	IN	HKM 884V	BI VRT/SL3/6LXB	VRT/SL3/2211	ECW	23996	H43/31F	Feb-80	Rapson (SN)	Jun-05	
325	A	FAO 426V	BI VRT/SL3/6LXB	VRT/SL3/2123	ECW	23634	H43/31F	Jan-80	Rapson (SN)	Jun-05	
326	T	KVF 246V	BI VRT/SL3/6LXB	VRT/SL3/2251	ECW	24063	H43/32F	Mar-80	Rapson (SN)	Jun-05	
328	F	PWY 49W	BI VRT/SL3/6LXB	VRT/SL3/2856	ECW	24359	H43/31F	Apr-81	Rapson (SN)	Jun-05	
330	T	VAH 280X	BI VRT/SL3/6LXB	VRT/SL3/3071	ECW	24922	H43/31F	Aug-81	Rapson (SN)	Jun-05	
351	F	B803 AOP	MCW DR102/27	MB7877	MCW		H43/30F	Oct-84	Rapson (SN)	Jun-05	
352	IN	SHE 306Y	Ld ONLXB/1R	ON357	ECW	25258	H45/32F	Oct-82	Rapson (SN)	Jun-05	
353	A	UDT 312Y	Ld ONLXB/1R	ON686	ECW	25609	H45/32F	Jun-83	Rapson (SN)	Jun-05	
354	wdn	CWR 510Y	Ld ONLXB/1R	ON368	ECW	25231	H45/32F	Oct-82	Rapson (SN)	Jun-05	
355	IN	EEH 905Y	Ld ONLXB/1R	ON750	ECW	25629	H45/32F	Jul-83	Rapson (SN)	Jun-05	
356	F	B742 GSC	Ld ONTL11/2R	ON1444	ECW	25973	H51/32F	Oct-84	Rapson (SN)	Jun-05	
357	IN	B743 GSC	Ld ONTL11/2R	ON1454	ECW	25974	H51/32F	Oct-84	Rapson (SN)	Jun-05	
358	IN	B744 GSC	Ld ONTL11/2R	ON1455	ECW	25975	H51/32F	Oct-84	Rapson (SN)	Jun-05	
359	IN	B745 GSC	Ld ONTL11/2R	ON1456	ECW	25976	H51/32F	Oct-84	Rapson (SN)	Jun-05	
360	IN	C791 SFS	Ld ONTL11/2R	ON2237	ECW	26273	H51/32F	Jan-86	Rapson (SN)	Jun-05	
361	F	C794 SFS	Ld ONTL11/2R	ON2243	ECW	26280	H51/32F	Jan-86	Rapson (SN)	Jun-05	
401	T	MIL 9753	Vo B10M-61	18164	Pn	8812VMH3C844	C53F	Jan-89	Rapson (SN)	Jun-05	F306 URU, ESK 985, TRM 144
404	IN	YAZ 6428	Vo B10M-60	21441	Pn 11/93 Pe350	9312VCP2003R	C48FT	Oct-89	Rapson (SN)	Jun-05	G260 UAS, 318 DHR, ESK 985
406	IN	MIL 9755	Vo B10M-60	23625	Pn	9012VCB1623	C44FT	Jan-90	Rapson (SN)	Jun-05	G811 BPG
410	T	G149 YAS	Vo B10M-60	23897	Pn	9012VCAP1814	C53F	Apr-90	Rapson (SN)	Jun-05	G512 EFX, 3275 RU, G264 NUX, TFX 966, MIL 5573
441	P	JAZ 9853	Vo B10M-61	7489	VH	11558	C52FT	Aug-84	Rapson (SN)	Jun-05	B217 FJS
450	T	JAZ 9855	Vo B10M-56	9217	Pn	8511VZP2C02N	C46FT	Aug-85	Rapson (SN)	Jun-05	C330 FSU, ESK 983, 318 DHR
454	Int	KLZ 2318	Vo B10M-61	12416	Pn	8712VUP3C004	C55F	Nov-86	Rapson (SN)	Jun-05	D181 TSB
459	T	D660 XPS	Vo B10M-61	13654	Du	8696/0362	C57F	Apr-87	Rapson (SN)	Jun-05	
460	T	KLZ 2315	Vo B10M-60	21437	Pn	8912VCAP1076	C57F	May-89	Rapson (SN)	Jun-05	F828 APS
461	T	F469 WFX	Vo B10M-60	21221	Pn	8912VCAP1391	C53F	Apr-89	Rapson (SN)	Jun-05	
462	T	MIL 9754	Vo B10M-60	24161	Pn	9012VCB1896	C46FT	Apr-90	Rapson (SN)	Jun-05	G251 VPK
463	T	MIL 9756	Vo B10M-60	24158	Pn	9012VCB1897	C46FT	Apr-90	Rapson (SN)	Jun-05	G252 VPK
464	T	G253 VPK	Vo B10M-60	24160	Pn	9012VCB1898	C46FT	Apr-90	Rapson (SN)	Jun-05	
467	KY	J 75 FPS	Vo B10M-60	22688	Pn	8912VCA1704	C57F	Aug-91	Rapson (SN)	Jun-05	J 75 FPS, KLZ 2317
468	F	H410 DPS	Vo B10M-60	22687	Pn	8912VCA1702	C57F	Jan-91	Rapson (SN)	Jun-05	H410 DPS, KLZ 2316
471	KY	B450 GCB	Vo B10M-61	9487	VH	11734	C49FT	Mar-85	Rapson (SN)	Jun-05	B471 UNB, XTW 359, B450 GCB, RIB 8035
488	P	G636 WJS	Ds Jv	125DL1909/429	Du	8824/0964	B67F	Aug-89	Rapson (SN)	Jun-05	
489	IN	R849 CJS	Ds Jv	SFD721BR3VGJ22039	UVG	5696/98	DP69F	Jan-98	Rapson (SN)	Jun-05	
490	T	R412 YWJ	Ds Jv	SFD721BR3VGJ21976	Pn	9712HFM6746	DP67F	Apr-98	Rapson (SN)	Jun-05	R412 YWJ, OFA 990
491	IN	FSU 718	Ds Jv	SFD721BR3VGJ21977	Pn	9712HFM6747	DP67F	Apr-98	Rapson (SN)	Jun-05	R413 YWJ
492	P	S690 RWG	Ds Jv	SFD721BR3WJE2166	Pn	9812GHM9478	DP67F	Oct-98	Rapson (SN)	Jun-05	S690 RWG, LTU 284
493	P	SY 51 EZU	Ds Jv	SFD721BR41GJ22355	Pn	-?-	DP70F	Feb-02	Rapson (SN)	Jun-05	
494	P	SY 51 EHT	Ds Jv	SFD721BR41GJ22344	Pn	-?-	DP70F	Jan-02	Rapson (SN)	Jun-05	

495	F	SY 51 EHU	Ds Jv	SFD721BR41GJ22346	Pn	-?-	DP70F	Jan-02	Rapson (SN)	Jun-05		
496	KY	SY 51 EHZ	Ds Jv	SFD721BR41GJ22347	Pn	-?-	DP70F	Jan-02	Rapson (SN)	Jun-05		
497	P	SY 51 EHV	Ds Jv	SFD721BR41GJ22348	Pn	-?-	DP70F	Jan-02	Rapson (SN)	Jun-05		
498	T	SY 51 EHX	Ds Jv	SFD721BR41GJ22349	Pn	-?-	DP70F	Jan-02	Rapson (SN)	Jun-05		
501	P	F 70 DDA	Ld LX2R11C15Z4R	LX1469	Ld		B49F	Jul-89	Rapson (SN)	Jun-05		
502	wdn	G 83 EOG	Ld LX2R11C15Z4R	LX1486	Ld		B49F	Aug-89	Rapson (SN)	Jun-05		
504	A	G103 EOG	Ld LX2R11C15Z4R	LX1526	Ld		B49F	Sep-89	Rapson (SN)	Jun-05		
508	P	G111 EOG	Ld LX2R11C15Z4R	LX1534	Ld		B49F	Sep-89	Rapson (SN)	Jun-05		
515	P	G132 EOG	Ld LX2R11C15Z4R	LX1565	Ld		B49F	Oct-89	Rapson (SN)	Jun-05		
517	A	G150 EOG	Ld LX2R11C15Z4R	LX1590	Ld		B49F	Oct-89	Rapson (SN)	Jun-05		
524	P	G173 EOG	Ld LX2R11C15Z4R	LX1635	Ld		B49F	Nov-89	Rapson (SN)	Jun-05		
526	P	G176 EOG	Ld LX2R11C15Z4R	LX1638	Ld		B49F	Dec-89	Rapson (SN)	Jun-05		
531	A	G284 EOG	Ld LX2R11C15Z4R	LX1823	Ld		B49F	Jun-90	Rapson (SN)	Jun-05		
534	A	G289 EOG	Ld LX2R11C15Z4R	LX1828	Ld		B49F	Jun-90	Rapson (SN)	Jun-05		
542	A	YX 05 FEK	Ds Jv	SFD????????22532	Pn	-?-	C70F	Apr-05	Rapson (SN)	Jun-05		
614		FSU 797	Vo B10M-62	040276	PMT		9412VUP1790	C48FT	Dec-93	Rapson (SN)	Jun-05	L591 RST, ESK 986
616	T	JAZ 9854	Vo B10M-60	28598	Pn		9112VCP0443	C49FT	Mar-92	Rapson (SN)	Jun-05	J738 CWT, 448 GWL
617	T	OIL 4570	Vo B10M-60	28594	Pn		9112VCP0442	C49FT	Mar-92	Rapson (SN)	Jun-05	J737 CWT, ESK 932
619	T	930 GJF	Vo B10M-60	31802	Pn		9312VCP1019	C53F(T?)	Jun-93	Rapson (SN)	Jun-05	K 65 BKG
620	T	OFA 990	DAF SB3000DKV601	000381	VH		30550	C51FT	Apr-92	Rapson (SN)	Jun-05	J 26 LRN, ESK 981
621	T	673 EXA	DAF SB3000DKV601	000307	VH		30542	C55F	Feb-92	Rapson (SN)	Jun-05	J 64 GCX
623	RC	RIB 8035	Vo B10M-62	40580	Je		23313	C48FT	Mar-94	Rapson (SN)	Jun-05	L947 NWW, 3692 NT
624	T	N583 DAS	Vo B10M-62	43235	Pn		9512VUP4441	C46FT	Aug-95	Rapson (SN)	Jun-05	N139 YST, 3692 NT
625	RC	KLZ 2316	Vo B10M-62	41592	Pn		9412VUP2186	C51FT	Jan-95	Rapson (SN)	Jun-05	M488 WAS, ESK 983
626	IN	HDZ 5407	Vo B10M-62	042771	PMT		9512VUP3599	C47FT	Apr-95	Rapson (SN)	Jun-05	M 45 KAX, 9637 EL
627	P	CXP 742	Vo B10M-62	41141	Pn		9412VUM2174	C49FT	Jun-94	Rapson (SN)	Jun-05	L 9 TCC
628	RC	650 GXJ	Vo B10M-62	43572	Pn		9512VUP3799	C47FT	May-96	Rapson (SN)	Jun-05	N764 CAS
629	RC	YBZ 818	Vo B10M-62	44118	Pn		9512VUP3828	C48FT	Jan-96	Rapson (SN)	Jun-05	N905 AAS
631	RC	LJ 595	Ka S250	WKK13400001015009	Ka			C55FT	Jun-95	Rapson (SN)	Jun-05	M972 NFU
633	F	EUI 656	Ds Jv	12SDA2159/1500	Bf		3115	C49F	May-96	Rapson (SN)	Jun-05	N865 XMO
634	RC	KLZ 858	Vo B10M-62	YV31M2B115A043500	Pn		9512VUP3793	C49FT	Jan-97	Rapson (SN)	Jun-05	P491 FAS
635	RC	900 HKU	Vo B10M-62	YV31M2B10TA044073	Pn		9512VUP4468	C49FT	Jan-97	Rapson (SN)	Jun-05	P492 FAS
636	F	IDZ 636	Vo B10M-62	44074	Pn		9512VUP4469	C49FT	Apr-97	Rapson (SN)	Jun-05	P649 FST
637	F	162 EKH	Vo B10M-62	41894	Pn		9412VUP2198	C51FT	Apr-95	Rapson (SN)	Jun-05	95-G-955, M105 VRA
638	RC	P869 SSK	Vo B10M-62	60180	Je Mistral		24200	C53FT	Apr-97	Rapson (SN)	Jun-05	P648 NST, 4234 NT, 540 FFX
639	RC	719 CEL	DAF DE33WSSB3000	005689	VH		32852	C50FT	Aug-97	Rapson (SN)	Jun-05	R272 FBX
640	RC	MIL 5573	Vo B10M-62	YV31MA611VC060469	Je		24617	C43FT	Jan-98	Rapson (SN)	Jun-05	R775 PST, WXI 878
641	RC	NFL 881	Vo B10M-62	YV31MA61XVC060874	Pn		9712VUP8654	C50FT	May-98	Rapson (SN)	Jun-05	R872 RST
643	F	R874 RST	Vo B10M-62	YV31MA617VA047452	Pn		9712VUM7236	C53FT	May-98	Rapson (SN)	Jun-05	
644	IN	T131 AST	Vo B10M-62	YV31MA612VA046415	Pn		9812VUM8677	C49FT	Mar-99	Rapson (SN)	Jun-05	
645		V943 JST	Vo B10M-62	060875	PMT		9812VUP8655	C49FT	Jan-00	Rapson (SN)	Jun-05	V943 JST, TRM 144
646	RC	V944 JST	Vo B10M-62	YV31MA612WC060997	Pn		9812VUP9721	C49FT	Jan-00	Rapson (SN)	Jun-05	
647	RC	W743 NAS	Vo B10M-62	YV31MA618YA051574	Pn Paragon		9912VUT1685	C49FT	May-00	Rapson (SN)	Jun-05	
648	RC	XIJ 602	Vo B10M-62	YV31MA616YA051668	Pn Paragon		9912VUT1688	C49FT	May-00	Rapson (SN)	Jun-05	W744 KAS
649	RC	W745 NAS	Vo B10M-62	51575	Pn Paragon		-?-	C49FT	May-00	Rapson (SN)	Jun-05	
650	RC	444 VNX	Vo B10M-62	YV31MA614YA051667	Pn Paragon		-?-	C49FT	May-00	Rapson (SN)	Jun-05	W746 KAS
651	RC	GSU 375	Vo B10M-62	42504	Je		23596	C53FT	May-95	Rapson (SN)	Jun-05	M307 KRY
652	T	MIL 9752	Vo B10M-60	20626	Pn		8912VCB1339	C53F	Mar-89	Rapson (SN)	Jun-05	F437 DUG, DSK 558, F437 DUG
653	F	Y285 VST	Vo B10M-62	61318	Pn Excalibur		-?-	C49FT	Mar-01	Rapson (SN)	Jun-05	
654	RC	KLZ 2317	Vo B10M-62	YV31MA6111A052698	Pn		0012VUP3274	C49FT	Feb-01	Rapson (SN)	Jun-05	X465 SAS, MXI 694
655	RC	X466 SAS	Vo B10M-62	61310	Pn Pre 350		-?-	C49FT	Jan-01	Rapson (SN)	Jun-05	
656	RC	318 DHR	Vo B10M-62	61206	Pn		9912VUP0536	C48FT	May-99	Rapson (SN)	Jun-05	T536 EUB
657	RC	LTU 284	Vo B10M-62	61192	Pn		9912VUP0539	C48FT	May-99	Rapson (SN)	Jun-05	T539 EUB, ESK 985
658	T	T535 EUB	Vo B10M-62	61193	Pn		9912VUP0535	C48FT	Apr-99	Rapson (SN)	Jun-05	T535 EUB, TRM 144
660	RC	TFX 966	Vo B10M-62	60055	VH		32539	C53F	Apr-96	Rapson (SN)	Jun-05	9396 WW, N330 RGB

Highland Country: Fleetlist, 31 January 2006

<b>662</b>	RC	<b>448 GWL</b>	Vo B10M-62	042177	VH	32203	C46FT	Feb-95	Rapson (SN)	Jun-05	M688 KVVU
<b>663</b>	P	<b>S494 UAK</b>	Ds Jv	SFD721BR3WGJE2158	Pn	9812GHM8870	C67F	Aug-98	Rapson (SN)	Jun-05	S494 UAK, KFO 809
<b>664</b>	P	<b>WFO 311</b>	Ds Jv	SFD721BR3WGJE2161	Pn	9812GHM8871	C50FT	Sep-98	Rapson (SN)	Jun-05	S495 UAK
<b>665</b>	T	<b>J257 NNC</b>	Vo B10M-60	028165	VH	30945	C49F	Feb-92	Rapson (SN)	Jun-05	J257 NNC, 804 TYA, J257 NNC, 200 UWX
<b>667</b>	RC	<b>DSU 707</b>	Vo B10M-62	052311	Pn	0012VUT3406	C49FT	Jan-01	Rapson (SN)	Jun-05	X 47 CNY
<b>668</b>	RC	<b>900 RWX</b>	Vo B10M-62	052696	Pn	0012VUT3408	C49FT	Jan-01	Rapson (SN)	Jun-05	X 48 CNY
<b>669</b>	RC	<b>FN 04 JZR</b>	Vo B12M	YV3R9G11X4A011859	Je	-?-	C49FT	Jun-04	Rapson (SN)	Jun-05	
<b>670</b>	RC	<b>FN 04 JZT</b>	Vo B12M	YV3R9G1164A011860	Je	26858	C49FT	Jun-04	Rapson (SN)	Jun-05	
<b>671</b>		<b>850 RFX</b>	Vo B10M-62	045257	VH	32569	C48FT	Jun-96	Rapson (SN)	Jun-05	N 90 TGM